



GE
Lighting

25936 - GE A21 - Long Life

200A21/99/IF

NOTES

Burn BDTH but avoid horizontal burning with support spine beneath filament to prevent premature arcing.

Jun 1, 2017 4:11:57 PM For additional information, visit www.gelighting.com